

HABS
SC
44-UNI,
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

CARNEGIE FREE LIBRARY
300 E. South Street
Union
Union County
South Carolina

HABS No. SC-618

Jack Boucher, photographer, March 1987

- SC-618-1 NORTH (FRONT) FACADE, LOOKING SOUTH
- SC-618-2 NORTH (FRONT) FACADE, LOOKING SOUTH, WITH SCALE
- SC-618-3 NORTH (FRONT) FACADE, LOOKING SOUTHWEST
- SC-618-4 NORTH (FRONT) FACADE, LOOKING NORTHEAST
- SC-618-5 NORTH (FRONT) FACADE, MAIN ENTRYWAY
- SC-618-6 NORTH (FRONT) FACADE, MAIN ENTRYWAY, WITH SCALE
- SC-618-7 NORTH (FRONT) FACADE, EAST SIDE
- SC-618-8 NORTH (FRONT) FACADE, EAST SIDE, WITH SCALE
- SC-618-9 WEST SIDE ELEVATION, LOOKING NORTHEAST
- SC-618-10 VIEW OF CUPOLA, LOOKING NORTHEAST
- SC-618-11 INTERIOR, NORTH (FRONT) VESTIBULE, UNDER DOME, LOOKING NORTHWEST
- SC-618-12 INTERIOR, NORTH (FRONT) VESTIBULE, VIEW OF STAINED GLASS UNDER DOME

HABS
SC
44-UNI,
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO
CARNEGIE FREE LIBRARY
300 E. South Street
Union
Union County
South Carolina

HABS No. SC-618
(p. 2)

SC-618-1 through SC-618-12 were previously transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, March 1987

SC-618-13 (CT) NORTH (FRONT) FACADE, LOOKING NORTHEAST

SC-618-14 (CT) VIEW OF CUPOLA, LOOKING NORTHEAST

SC-618-15 (CT) INTERIOR, NORTH (FRONT) VESTIBULE, VIEW OF STAINED GLASS UNDER DOME